



**INDUSTRY:**  
**Packaging Manufac-**  
**turer**

**APPLICATION:**  
**Bottle top line**



**Customer Case Study**  
**Location: Scotland**

**Have you experienced  
this issue with your  
bottle top line?**

#### SITUATION APPRAISAL ———

A Scottish packaging manufacturer had won an order for 5 million bottle tops from a major American whisky brand. Upon delivery of the bottle tops, they did not pass safety inspections as the bottle tops had traces of grease on them which was not food-grade. The products were rejected.

#### OUTCOMES ———

Other lubricant suppliers suggested products but as many were white in colour, they didn't show up under their UV control lights. Our team attended the site with SKF. They proposed a food-grade grease that was detectable under all their CQ measures.

#### COST SAVING RESULT ———

The rejection of the previous order due to contamination cost them around 50K, so with the change to the SKF food-grade grease, that risk is eradicated in future.

**MAKING INDUSTRY MORE PROFITABLE**